



# 2017 Inboard Inspectors Test

Note: All Inspectors who have not submitted and passed the 2017 Inspectors test by May 15, 2017 will have their names removed from the list of Approved Inspectors until such time as they have successfully passed the examination.

Answer the questions below using APBA Bylaws, APBA General Safety Rules, Inboard Rules, and the Capsule Requirements document found in "Resources" on the APBA website. Please answer True or False only.

1. The Association logo can be placed anywhere the competitor chooses.
2. As long as an image recording device is small (such as a GoPro) and has a quick disconnect attachment, it is acceptable for use on the driver's helmet.
3. A contestant can be declared illegal in the runabout classes if they do not meet the lifting requirement for inspection.
4. Restraint system meeting SFI Spec 16.1 must be updated at two-year intervals from date of manufacture.
5. The cell manufacturers label has to be affixed to the cell?
6. All Drivers in capsule boats must have audio communication from a Spotter on shore and the Spotter must be stationed in immediate proximity to the Referee or his/her designee.
7. Fuels may be mixed as long as they pass the Digatron test and are on approved fuels list.
8. Where a carburetor spacer is allowed, the maximum thickness shall be measured at the greatest thickness of the spacer or wedge.
9. An aftermarket block may be used in the SE class.
10. Runabout class bottoms shall have no more than 3/8 inch concavity from keel to chine, from trailing edges to amidship.
11. All legal 5L boats are considered legal boats in the 2.5 Modified class.
12. Lifting slings must be pull tested every 2 years and documentation provided to inspector.
13. Where repairs are made during a race, the boat must be inspected and approved upon completion of such repairs in order to continue in competition.
14. All life jackets shall have at least 50% of the upper surfaces above the waist, both front and back, international orange or yellow in color.
15. A camshaft for a 350 engine used in the five litre class can only be purchased through the APBA/ACHA offices.
16. A Holley 0-4412BKX carb is legal for use in the 2.5 Stock class.

17. The Inspectors shall have the power after the finish of any race to order any contestant to dismantle his motor for inspection and measurement. Any contestant refusing to comply with the orders of the Inspector shall be disqualified by the Referee.
18. Competitors may place artwork or writing in the area across the front of the helmet directly above the opening as long as it does not exceed 8" wide X 2" high.
19. In the GP class fuel injection systems must be injected by a maximum of eight (8) hat nozzles using a cast aluminum injector throttle body available from a major manufacturer.
20. Color: Blue Specific Gravity:0.716 Digatron: -87 are the properties of Sunoco Supreme 112 fuel?
21. A prop shaft release is required in the SE class.

Upon completion of this test, submit to Brian Hajny, Inboard Chief  
Inspector by one of the following methods:  
Email: [brihaj@comcast.net](mailto:brihaj@comcast.net)  
USPS: Brian Hajny  
21011 178<sup>th</sup> St. Ct. E  
Orting Wa. 98360